


Product Announcement


Thicker Shoe Used on Band Brake Assembly

BRAKEPART 019 on Opera-SH >>>



BRAKEPART 019

SHOE 026
Thicker metal
band is used



Fiber brake
band

close up
front view

Manaras-Opera Improves It's Band Brake Assembly

Manaras-Opera is pleased to advise that it has made an improvement to it's band brake. This improvement applies to: **OSH/OGH/MGH/MGT/MTBH/MSL/MGSL, BRAKE 011/012/013, MOD 111.**

What was improved

- A thicker metal band **SHOE 026** is being used to support the fiber brake band in our brake assembly **BRAKEPART 019**.
- Improving to **SHOE 026** increases the life span of the brake band, as well as increases the time between maintenance adjustments or component replacements.
- Please note that the replacement component **BRAKEPART 019** replaces **BRAKEPART 017** in the above mentioned assemblies as well as for replacement components.

This improvement is available as of October 2009.
For further information, please contact your Manaras-Opera sales representative.

Toll free number: 800 - 361 - 2260
www.manaras.com